
Sides	Interior angle	Mitre saw setting
3	60.00°	60.00°
4	90.00°	45.00°
5	108.00°	36.00°
6	120.00°	30.00°
7	128.57°	25.71°
8	135.00°	22.50°
9	140.00°	20.00°
10	144.00°	18.00°
11	147.27°	16.36°
12	150.00°	15.00°